

(ASSISTANT ENGINEER/ASSISTANT EXECUTIVE ENGINEER)

NO: AE/LSGD/NDL/FIT/21/2023-24

1. Name of school : LITTLE FLOWER, SENIOR SECONDARY SCHOOL, KARUVANCHAL
2. Name of officer : DHANYA U K.
3. Location : Karuvanchal
4. Period for which the certificate is issued : 2023-24
5. Type of building : Permanent

6.15x6.15x3.60 M 6 Class Rooms (G.F)

6.15x6.15x3.60 M 1 Class Room (G.F)

6.15x6.15x3.60 M 1 Office Room (G.F)

6.15x6.15x3.60 M 7 Class Rooms (F.F)

6.15x6.15x3.60 M 1 Computer Lab (F.F)

6.15x6.15x3.60 M 8 Class Rooms (S.F)

9.20x6.20x3.60 M 2 Class Rooms (G.F)

9.20x6.20x3.60 M 2 Science Labs (G.F)

6.20x6.20x3.60 M 1 Office Room (G.F)

3.00x3.00x3.60 M 1 Dark Room (G.F)

3.00x3.00x3.60 M 1 Store Room (G.F)

9.20x6.20x3.60 M 1 Biology Room (F.F)

9.20x6.20x3.60 M 3 Class Rooms (F.F)

6.20x6.20x3.60 M 1 Staff Room (F.F)

6.20x6.20x3.60 M 1 Library Room (F.F)

3.00x6.20x3.60 M 1 Stock Room (F.F)

ASSISTANT ENGINEER
LD & EW
NADUVIL PIN - 670 582



6. Nature of defect if any

- a. Foundation and basement : NIL
- b. Superstructure : NIL
- c. wood work wrought and put up : NIL
- d. Roof : NIL
- e. Flooring : NIL

f. Miscellaneous (Cracks if any) : NIL

7. Any major defects notice which will

Render the building unsafe in any manner : No

8. Whether maintenance works have been

done Properly : YES

9. Whether the structure is sound for conducting classes : YES, up to 31/03/2024, Under normal weather condition

Note:-

1. The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

2. Any additional observation is deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the building was inspected by on 04.07.2023 and found to be fit for the period for the reason stated above.

Place : Naduvil

Date : 05/07/2023




ASSISTANT ENGINEER
LID & EW
NADUVIL. PIN - 670 582